

Release Note

Software Release 1.9.6

For AR100 Series Internet Routers

Introduction

Allied Telesyn announces the release of Software Release 1.9.6 for AR100 Series Internet Routers. This Release Note describes the new features in Software Release 1.9.6.

This Release Note should be read in conjunction with the AR100 Series Internet Router Software Reference for Software Release 1.9.4, available on the support site at www.alliedtelesyn.co.nz/support/ar100/.



WARNING: *Information in this document is subject to change without notice and does not represent a commitment on the part of Allied Telesyn International. While every effort has been made to ensure that the information contained within this document and the features and changes described are accurate, Allied Telesyn International cannot accept any type of liability for errors in, or omissions arising from the use of this information.*

Enhancements and Resolved Issues

Software release 1.9.6 includes the following resolved issue:

- A POTS connection between two telephones was sometimes low quality. This issue has been resolved.

Availability

Software Release 1.9.6 is available immediately as a FLASH release for upgrading existing routers. The release file can be downloaded directly from the Software Updates area of the Allied Telesyn web site at www.alliedtelesyn.co.nz/support/updates/patches.html or from the support site for your router: www.alliedtelesyn.co.nz/support/ar100/.

